

MONIT-AIR GROUP INC.

1949 FORMAN ROAD
JEFFERSON, OHIO
44047

PHONE: 440-992-1122
FAX: 440-563-5672

A CONCERN FOR THE ENVIRONMENT

**FIRELANDS
LOCAL
SCHOOLS
TRIENNIAL
AHERA
INSPECTION**

APRIL 29, 2015

MONIT-AIR GROUP INC.

1949 FORMAN ROAD
JEFFERSON, OHIO
44047

PHONE: 440-992-1122
FAX: 440-563-5672

A CONCERN FOR THE ENVIRONMENT

July 27, 2015

Mr. Charles Galloway
Supervisor of Buildings & Grounds
FIRELANDS LOCAL SCHOOLS
11970 Vermilion Road
Oberlin, Ohio 44074

Re: 3 year AHERA Re-Inspection


Dear Mr. Galloway,

Enclosed is the documentation of the 3-year re-inspection of asbestos containing materials that was recently completed for the school district. This material should be copied and placed in each Management Plan in the district. All asbestos containing materials should be maintained under the guidance of the school's O&M program.

I should like to remind you that yearly notifications concerning the ability of the Management Plan are required per the AHERA regulations.

Finally, I have enclosed an invoice for this service per our agreement. Please feel free to contact myself if you have any questions concerning the above, or with the Management Plan documentation.

Respectfully submitted,



Darrin Demshar
Certified Asbestos Hazard Evaluation Specialist
#34336

1(a)

Date of Inspection: A visual inspection of the school building's belonging to the Firelands Local School District which contains asbestos containing materials was conducted by John Murphy of Monit-Air Group Inc. on April 29, 2015. The purpose of the inspection was to re-inspect all asbestos containing materials, based on a previous inspection performed by a consulting firm other than Monit-Air Group Inc. in accordance with the AHERA regulations for all of the buildings owned or operated by the school district. All of the information gathered during the re-inspection was compiled into a comprehensive report that was presented to the school district. The report documents the conditions found at each of the buildings. A copy of this report is available for public inspection and review at the Board of Education offices for the school district.

DATE OF INSPECTION: APRIL 29, 2015

RE-INSPECTION CONDUCTED BY:

A handwritten signature in black ink, appearing to read 'DARRIN DEMSHAR', is written over a circular stamp or seal.

**DARRIN DEMSHAR
ASBESTOS HAZARD EVALUATION SPECIALIST
#34336**

1(b)

ASSESSMENTS: The AHERA regulations require that for each inspection and re-inspection conducted, the accredited inspector shall provide a written assessment of all ACBM to the person designated by the LEA for inclusion into the district's management plan. The inspector is required to classify all friable ACBM and suspected ACBM assumed to be ACM in the school building into one of the following seven categories:

1. Damaged or significantly damaged thermal system insulation.
2. Damaged friable surfacing ACM.
3. Significantly damaged friable surfacing ACM.
4. Damaged or significantly damaged friable miscellaneous ACM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

The following assessments of ACBM were generated from the AIMS database by indexing the appropriate fields of data and interfacing the output with a word processing program. Each type of ACBM is then assessed from the information provided on the recording forms for assessment data into one of the seven categories in AHERA, and the results are compiled onto a computer generated inventory listing the location and amount of material, the overall condition of the material and preventive measures which might eliminate the reasonable likelihood of undamaged ACM from becoming significantly damaged. The following assessments are grouped into the above listed categories, and are sub-grouped by building within each category.

SECTION 1 (b). 1
Areas Containing Damaged and Significantly Damaged Thermal System
Insulation

SCHOOL NAME: FIRELANDS LOCAL SCHOOL DISTRICT

Functional Area	Rm. No.	Fl. No.	SF LF	Material Type	Material Description	Percent Damage	Damage/ Change Description
-----------------	---------	---------	-------	---------------	----------------------	----------------	----------------------------

NONE

SECTION 1 (b). 2
Areas Containing Damaged Surfacing Material

SCHOOL NAME: FIRELANDS LOCAL SCHOOL DISTRICT

Functional Area	Rm. No.	Fl. No.	SF LF	Material Type	Material Description	Percent Damage	Damage/ Change Description
-----------------	---------	---------	-------	---------------	----------------------	----------------	----------------------------

NONE

SECTION 1 (b). 3
Areas Containing Significantly Damaged Surfacing Material

SCHOOL NAME: FIRELANDS LOCAL SCHOOL DISTRICT

Functional Area	Rm. No.	Fl. No.	SF LF	Material Type	Material Description	Percent Damage	Damage/ Change Description
-----------------	---------	---------	-------	---------------	----------------------	----------------	----------------------------

NONE

SECTION 1 (b). 4

Areas Containing Significantly Damaged Friable Miscellaneous ACM

SCHOOL NAME: FIRELANDS LOCAL SCHOOL DISTRICT

Functional Area	Rm. No.	Fl. No.	SF LF	Material Type	Material Description	Percent Damage	Damage/ Change Description
-----------------	---------	---------	-------	---------------	----------------------	----------------	----------------------------

NONE

SECTION 1 (b). 5
Areas Containing ACM with Potential for Damage

SCHOOL NAME: FIRELANDS HIGH SCHOOL

Functional Area	Rm. No.	Fl. No.	SF LF	Material Type	Material Description	Percent Damage	Damage Description
BOILER ROOM	1ST.FL.		1 TSI	ASBESTOS INSULATED FIRE DOOR		0%	NONE
WEIGHT ROOM	RM. 200		650 SQ.	VAT RED FLOOR TILE & MASTIC		0%	NONE
WEIGHT ROOM	RM. 200		4 TSI	CEMENTITIOUS PIPE ELBOWS & JOINTS		0%	NONE
OFFICE	RM. 200		100 SQ.	VAT RED FLOOR TILE & MASTIC		0%	NONE
SHOP TOOL RM.	1ST.FL.		100 SQ.	VAT RED FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.156		10 TSI	CEMENTITIOUS PIPE ELBOWS & JOINTS		0%	NONE
VO/AG SHOP	RM.122		7 TSI	CEMENTITIOUS ELBOWS ON ROOF DRAINS		0%	NONE
CLASSROOM	RM.120		650 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
OFFICE	RM.122		100 SQ.	VAT WHITE FLOOR TILE & MASTIC		0%	NONE/ UNDER CARPET
FACULTY WORKROOM	1ST.FL.		150 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
CONFERENCE ROOM	1ST.FL.		100 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
AV WORKROOM	1ST.FL.		120 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.124		650 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
MACHINE BAY	RM.129		150 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
MACHINE BAY	RM.129		500 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.126		650 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
MUSIC ROOM	1ST.FL.		1000SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
PRACTICE ROOM	1ST.FL.		50 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
PRACTICE ROOM	1ST.FL.		50 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
MUSIC OFFICE	1ST.FL.		100 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
INSTRUMENT STORAGE	1ST.FL.		150 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.121		650 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.123		650 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
STORAGE ROOM	1ST.FL.		100 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
NORTH CORRIDOR	1ST.FL.		1200 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.108		650 SQ.	VT RED FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.109		650 SQ.	VT GREEN FLOOR TILE & MASTIC		0%	NONE
NW CORRIDOR	1ST.FL.		180 SQ.	CEMENT ASBESTOS WALL BOARD		0%	NONE
NW CORRIDOR	1ST.FL.		1000 SQ.	VAT GREEN FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.111		650 SQ.	VAT BROWN/BEIGE FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.110		650 SQ.	VAT BROWN/BEIGE FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.113		650 SQ.	VAT BROWN/BEIGE FLOOR TILE & MASTIC		0%	NONE
CONFERENCE ROOM	1ST.FL.		200 SQ.	VAT RED FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	139/141		650 SQ.	VAT BROWN/BEIGE FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.107		650 SQ.	VT GREEN FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.105		160 SQ.	TRANSITE COUNTERTOP		0%	NONE
CLASSROOM	RM.104		650 SQ.	VT RED FLOOR & MASTIC		0%	NONE
CLASSROOM	RM. 113		650 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
PREP ROOM	RM.103		120 SQ.	VT GREEN FLOOR & MASTIC		0%	NONE
CLASSROOM	RM.103		40 SQ.	TRANSITE COUNTERTOPS		0%	NONE
CLASSROOM	RM.103		650 SQ.	VT GREEN FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.102		650 SQ.	VAT RED FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.101		650 SQ.	VT GREEN FLOOR TILE & MASTIC		0%	NONE
PREP ROOM	RM.101			2 CEMENTITIOUS PIPE ELBOWS & JOINTS		0%	NONE
JANITOR STORAGE	1ST.FL.		10 FT.	PAPER PIPE INSULATION		0%	NONE

SECTION 1 (b). 5
Areas Containing ACBM with Potential for Damage

SCHOOL NAME: FIRELANDS HIGH SCHOOL

Functional Area	Rm. No.	Fl. SF No. LF	Material Type	Material Description	Percent Damage	Damage Description
CLASSROOM	RM.115	650 SQ.	VAT RED FLOOR TILE & MASTIC		0%	NONE
STAGE	1ST.FL.	100 FT.	BLOCK PIPE INSULATION		0%	NONE
STAGE	1ST.FL.	80 FT.	BLOCK PIPE INSULATION		0%	NONE
KITCHEN CORRIDOR	1ST.FL.	20 FT.	PAPER PIPE INSULATION		2%	EXPOSED END
KITCHEN	1ST.FL.	250 SQ.	VT WHITE FLOOR & MASTIC		0%	NONE
CAFETERIA	1ST.FL.	1500 SQ.	VT WHITE FLOOR & MASTIC		0%	NONE
KITCHEN RESTROOM	1ST.FL.	15 FT.	BLOCK PIPE INSULATION		0%	NONE
RESTROOM	1ST.FL.	150 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
CENTRAL OFFICE	1ST.FL.	250 SQ.	VT GREEN FLOOR TILE & MASTIC		0%	NONE
CENTRAL OFFICE	1ST.FL.	12 FT.	BLOCK PIPE INSULATION		0%	NONE
ASST PRINCIPAL OFFICE	1ST.FL.	20 SQ.	VT BLACK FLOOR & MASTIC		0%	NONE
ASST PRINCIPAL OFFICE	1ST.FL.	15 FT.	BLOCK PIPE INSULATION		0%	NONE
ASST PRINCIPAL OFFICE	1ST.FL.	120 SQ.	VT GREY FLOOR & MASTIC		0%	NONE
ASST PRINCIPAL OFFICE	1ST.FL.	10 FT.	BLOCK PIPE INSULATION		0%	NONE
CONFERENCE ROOM	1ST.FL.	150 SQ.	VT GREEN FLOOR TILE & MASTIC		0%	NONE
CONFERENCE ROOM	1ST.FL.	12 FT.	BLOCK PIPE INSULATION		5%	SMALL TEAR
OFFICE RESTROOM	1ST.FL.	30 SQ.	VT GREEN FLOOR TILE & MASTIC		0%	NONE
OFFICE STORAGE	1ST.FL.	6 FT.	BLOCK PIPE INSULATION		0%	NONE
CLINIC	1ST.FL.	200 SQ.	VT GREEN FLOOR TILE & MASTIC		0%	NONE
PRINCIPAL OFFICE	1ST.FL.	240 SQ.	VT GREY FLOOR & MASTIC		0%	NONE
PRINCIPAL OFFICE	1ST.FL.	15 FT.	BLOCK PIPE INSULATION		0%	NONE
PA ROOM	1ST.FL.	50 SQ.	VT GREEN FLOOR TILE & MASTIC		0%	NONE
CLASSROOM/ A.D.	RM.100	650 SQ.	VT GREEN FLOOR TILE & MASTIC		0%	NONE
STORAGE ROOM	RM.100	100 SQ.	VT GREEN FLOOR TILE & MASTIC		0%	NONE
STORAGE ROOM	RM.100	10 FT.	BLOCK PIPE INSULATION		0%	NONE
CLASSROOM	RM.203	650 SQ.	VAT RED FLOOR TILE & MASTIC		0%	NONE
FACULTY MEN'S R.R.	2ND.FL.	30 SQ.	VT GREY FLOOR TILE & MASTIC		0%	NONE
FACULTY WOMEN'S R.R.	2ND.FL.	30 SQ.	VT GREEN FLOOR TILE & MASTIC		0%	NONE
CEILING PLENUM	1ST.FL.		BLOCK PIPE INSULATION ABOVE CEILING		5%	WATER DAMAGE
CLASSROOM	RM. 302	650 VAT	VAT RED FLOOR TILE & MASTIC		0%	NONE
CORRIDORS		2500 SQ.	TRANSITE WALL PANELS		0%	NONE

SECTION 1 (b). 5
Areas Containing ACBM with Potential for Damage

SCHOOL NAME: BOARD OFFICE

Functional Area	Rm. No.	Fl. No.	SF LF	Material Type	Material Description	Percent Damage	Damage Description
FACULTY ROOM	1ST.FL.		10 TSI	CEMENTITIOUS PIPE ELBOWS & JOINTS		0%	NONE
LIBRARY AREA	1ST.FL.		1200 SQ.	VAT WHITE FLOOR TILE & MASTIC		0%	NONE
FACULTY RESTROOM	1ST.FL.		30 SQ.	VAT WHITE FLOOR TILE & MASTIC		0%	NONE
PRINCIPAL OFFICE	1ST.FL.		120 SQ.	VAT WHITE FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.100		800 SQ.	VAT WHITE/BLUE FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.101		800 SQ.	VAT WHITE/BLUE FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.102		800 SQ.	VAT WHITE/BLUE FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM. 103		800 SQ.	VAT WHITE/BLUE FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.104		800 SQ.	VAT WHITE/BLUE FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.105		800 SQ.	VAT WHITE/BLUE FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.130		800 SQ.	VAT WHITE/BLUE FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.132		800 SQ.	VAT WHITE/BLUE FLOOR TILE & MASTIC		0%	NONE
STORAGE CLOSET			100 SQ.	VAT WHITE FLOOR TILE & MASTIC		0%	NONE
STORAGE CLOSET			2 TSI	CEMENTITIOUS PIPE ELBOWS & JOINTS		0%	NONE
CLASSROOM	RM.108		800 SQ.	VAT WHITE/BLUE FLOOR TILE & MASTIC		0%	NONE
STORAGE CLOSET	RM.108		100 SQ.	VAT WHITE FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.106		800 SQ.	VAT WHITE/BLUE FLOOR TILE & MASTIC		0%	NONE
CEILING PLENUM	1ST.FL.		100 TSI	CEMENTITIOUS PIPE ELBOWS & JOINTS		0%	NONE

SECTION 1 (b). 5
Areas Containing ACM with Potential for Damage

SCHOOL NAME: SOUTH AMHERST MIDDLE SCHOOL

Functional Area	Rm. No.	Fl. No.	SF LF	Material Type	Material Description	Percent Damage	Damage Description
BOILER ROOM				1	ASBESTOS INSULATED FIRE DOOR	0%	NONE
CORRIDOR	BASEMENT		45 FT.		BLOCK PIPE INSULATION	0%	NONE
ART ROOM	RM. 090		15 FT		BLOCK PIPE INSULATION	0%	NONE
ART ROOM	RM.090		800 SQ.		VAT BROWN/BEIGE FLOOR TILE & MASTIC	0%	NONE/UNDER NEW TILE
BOYS RESTROOM	BASEMENT		40 FT.		BLOCK PIPE INSULATION	0%	NONE
STORAGE ROOM	RM.91		55 FT.		BLOCK PIPE INSULATION	0%	NONE
STORAGE ROOM	BASEMENT			10	CEMENTITIOUS PIPE ELBOWS & JOINTS	0%	NONE
STORAGE ROOM	BASEMENT		100 SQ.FT		TANK INSULATION	0%	NONE
GIRLS RESTROOM	BASEMENT		50 FT.		BLOCK PIPE INSULATION	0%	NONE
ART ROOM	BASEMENT		60 FT.		BLOCK PIPE INSULATION	0%	NONE
MAIN CORRIDOR	1ST.FL.		50 FT.		BLOCK PIPE INSULATION	0%	NONE
CLASSROOM	RM.101		10 FT.		PAPER PIPE INSULATION	0%	NONE
STAGE CORRIDOR	1ST.FL.			4	CEMENTITIOUS PIPE ELBOWS & JOINTS	0%	NONE
OFFICE CORRIDOR	1ST.FL.		900 sq.		ASBESTOS BOARD PANEL	0%	NONE
CAFETERIA	1ST.FL.		1200 SQ.		VAT BROWN FLOOR TILE & MASTIC	0%	NONE
KITCHEN	1ST.FL.		250 SQ.		VT WHITE FLOOR & MASTIC	0%	NONE
CAFETERIA RESTROOM	1ST.FL.		30 SQ.		VT WHITE FLOOR & MASTIC	0%	NONE
JANITORS CLOSET	1ST.FL.		35 FT.		PAPER PIPE INSULATION	0%	NONE
OFFICE STORAGE	1ST.FL.		100 SQ.		VAT GREY FLOOR TILE & MASTIC	0%	NONE
OFFICE STORAGE	1ST.FL.		12 FT.		PAPER PIPE INSULATION	0%	NONE
PRINCIPAL STORAGE	1ST.FL.		50 SQ.		VAT GREY FLOOR TILE & MASTIC	0%	NONE
LIBRARY OFFICE	RM.129		35 FT.		PAPER PIPE INSULATION	0%	NONE
CLASSROOM	RM. 130		800 SQ.		VT WHITE FLOOR & MASTIC	0%	NONE
LIBRARY	1ST.FL.		35 FT.		PAPER PIPE INSULATION	0%	NONE/ABOVE CEILING
CORRIDOR	1ST.FL.		60 FT.		PAPER PIPE INSULATION	5%	EXPOSED ENDS
CORRIDOR	2ND. FL.		600 SQ.		ASBESTOS BOARD PANEL	0%	NONE
CLASSROOM	RM. 221		800 SQ.		VAT BROWN FLOOR TILE & MASTIC	0%	NONE
CLASSROOM	RM.222		800 SQ.		VAT GREEN/GREY FLOOR TILE & MASTIC	0%	NONE
CLASSROOM	RM.217		800 SQ.		VAT BROWN FLOOR TILE & MASTIC	0%	NONE
OFFICE	RM.219		100 SQ.		VAT BROWN FLOOR TILE & MASTIC	0%	NONE
FACULTY LOUNGE	2ND.FL.		150 SQ.		VAT BROWN FLOOR TILE & MASTIC	0%	NONE
CLASSROOM	RM.209		800 SQ.		VT GREEN FLOOR TILE & MASTIC	0%	NONE
CLASSROOM	RM.214			1	TRANSITE SINK	0%	NONE
CLASSROOM	RM.214		800 SQ.		VAT GREY FLOOR TILE & MASTIC	0%	NONE
CHEMISTRY LAB	RM.220		150 SQ.		TRANSITE COUNTERTOP & HOOD	0%	NONE
CHEMISTRY LAB	RM.220		800 SQ.		VAT WHITE FLOOR TILE & MASTIC	0%	NONE
CLASSROOM	RM.202		800 SQ.		VAT WHITE FLOOR TILE & MASTIC	0%	NONE
OFFICE WORKROOM	2ND.FL.		120 SQ		VAT WHITE FLOOR TILE & MASTIC	0%	NONE
CEILING PLENUM	2ND.FL.		850 SQ.		CEILING PLASTER	5%	DAMAGED MATERIAL

SECTION 1 (b). 5
Areas Containing ACM with Potential for Damage

SCHOOL NAME: FIRELANDS ELEMENTARY

Functional Area	Rm. No.	Fl. No.	SF LF	Material Type	Material Description	Percent Damage	Damage Description
BOILER ROOM	1ST.FL.		1 OTHER	ASBESTOS INSULATED FIRE DOOR		0%	NONE
EAST CORRIDOR	1ST.FL.		540 SQ.	ASBESTOS WALL PANELS		0%	NONE
EAST CORRIDOR	1ST.FL.		1200 SQ.	VAT GREY FLOOR TILE & MASTIC		0%	NONE
GYMNASIUM	1ST.FL.		1800 SQ.	VAT GREY FLOOR TILE & MASTIC		0%	NONE
BOYS LOCKER ROOM	1ST.FL.		30 TSI	CEMENTITIOUS PIPE ELBOWS & JOINTS		0%	NONE
GIRLS LOCKER ROOM	1ST.FL.		8 TSI	CEMENTITIOUS PIPE ELBOWS & JOINTS		0%	NONE
GIRLS LOCKER STOR.	1ST.FL.		6 TSI	CEMENTITIOUS PIPE ELBOWS & JOINTS		0%	NONE
KITCHEN	1ST.FL.		10 TSI	CEMENTITIOUS PIPE ELBOWS & JOINTS		0%	NONE
STAGE	1ST.FL.		1200 SQ.	VAT GREY FLOOR TILE & MASTIC		0%	NONE
TUTOR ROOM	1ST.FL.		100 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
BACK GYM CORRIDOR	1ST.FL.		500 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.20		800 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	28/29		1000 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
PRACTICE ROOM	RM.1		80 SQ.	ASBESTOS BOARD PANEL		0%	NONE
PRACTICE ROOM	RM.1		50 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
PRACTICE ROOM	RM.2		80 SQ.	ASBESTOS BOARD PANEL		0%	NONE
PRACTICE ROOM	RM.2		50 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
MUSIC OFFICE	1ST.FL.		100 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
INSTRUMENT STORAGE	1ST.FL.		120 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.21		800 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.27		800 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.23		800 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.26		800 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.25		800 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.24		800 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
NORTH CORRIDOR	1ST.FL.		200 SQ.	ASBESTOS BOARD PANEL		0%	NONE
NORTH CORRIDOR	1ST.FL.		1200 SQ.	VAT GREY FLOOR TILE & MASTIC		0%	NONE
JANITORS CLOSET	1ST.FL.		10 TSI	CEMENTITIOUS PIPE ELBOWS & JOINTS		0%	NONE
PIPE CHASE	1ST.FL.		30 TSI	CEMENTITIOUS PIPE ELBOWS & JOINTS		5%	SMALL HOLES
OFFICE CORRIDOR	1ST.FL.		300 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
CENTRAL OFFICE	1ST.FL.		250 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
COPY ROOM	1ST.FL.		100 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
GUIDANCE OFFICE	1ST.FL.		100 SQ.	VAT GREY FLOOR TILE & MASTIC		0%	NONE
BOOK STORAGE	1ST.FL.		100 SQ.	VAT GREY FLOOR TILE & MASTIC		0%	NONE
PIPE CHASE	1ST.FL.		10 TSI	CEMENTITIOUS PIPE ELBOWS & JOINTS		10%	DAMAGED MATERIAL
WEST CORRIDOR	1ST.FL.		1100 SQ.	ASBESTOS BOARD PANEL		0%	NONE
WEST CORRIDOR	1ST.FL.		2500 SQ.	VAT GREY FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.1		800 SQ.	VAT WHITE FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.2		800 SQ.	VAT WHITE FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.3		800 SQ.	VAT WHITE FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.12		800 SQ.	VAT GREY FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.4		800 SQ.	VAT WHITE FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.11		800 SQ.	VAT GREY FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.5		800 SQ.	VAT BEIGE FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.10		800 SQ.	VAT RED FLOOR TILE & MASTIC		0%	NONE

SECTION 1 (b). 5
Areas Containing ACBM with Potential for Damage

SCHOOL NAME: FIRELANDS ELEMENTARY

Functional Area	Rm. No.	Fl. No.	SF LF	Material Type	Material Description	Percent Damage	Damage Description
CLASSROOM	RM.6		800 SQ.	VT BEIGE FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.9		800 SQ.	VAT RED FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.8		800 SQ.	VAT RED FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.7		800 SQ.	VT BEIGE FLOOR TILE & MASTIC		0%	NONE
JANITORS CLOSET	1ST.FL.		20 TSI	CEMENTITIOUS PIPE ELBOWS & JOINTS		0%	NONE
PIPE CHASE	1ST.FL.		10 TSI	CEMENTITIOUS PIPE ELBOWS & JOINTS		0%	NONE
TANK ROOM			125 TSI	ASBESTOS TANK INSULATION		0%	NONE
TANK ROOM			1 TSI	CEMENTITIOUS PIPE ELBOWS & JOINTS		0%	NONE

SECTION 1 (b). 6
Areas Containing ACBM with Potential for Significant Damage

SCHOOL NAME: FIRELANDS LOCAL SCHOOL DISTRICT

Functional Area	Rm. No.	Fl. No.	SF LF	Material Type	Material Description	Percent Damage	Damage/ Change Description
-----------------	---------	---------	-------	---------------	----------------------	----------------	----------------------------

NONE

SECTION 1 (b). 7

Areas Containing Any Remaining Friable or Friable Suspected ACBM

SCHOOL NAME: FIRELANDS LOCAL SCHOOL DISTRICT

Functional Area	Rm. No.	Fl. SF No. LF	Material Type	Material Description	Percent Damage	Damage/ Change Description
----------------------------	--------------------	--------------------------	--------------------------	---------------------------------	---------------------------	---------------------------------------

NONE

CERTIFICATION

I hereby certify that all of the work performed and assessments made thereon were done in accordance with the EPA Asbestos Hazard Emergency Response Act (AHERA) regulations.

Dated this 30th day of April, 2015

A handwritten signature in black ink, appearing to read 'Darrin Demshar', is written over a faint, circular stamp or seal.

Darrin Demshar
Asbestos Hazard Evaluation Specialist
#34336

1(c). RESPONSE ACTIONS RECOMMENDATIONS

1 (c) (l). Removal

It is recommended that the asbestos containing materials in the following areas with the school districts buildings be removed by a State of Ohio licensed Contractor. This recommendation is made after evaluating the information contained in the building inspection survey for ACBM, and is based upon the assessments made by the accredited building inspector. Final clearance samples are required to be collected for each project work area by a State licensed Asbestos Hazard Evaluation Specialist, and analyzed by a NVLAP accredited laboratory using either the AHERA protocol for TEM samples or the NIOSH 7400 method for PCM samples.

SCHOOL NAME: FIRELANDS LOCAL SCHOOL DISTRICT

Functional Area	Rm. No.	Fl. No.	SF LF	Material Type	Material Description	Percent Damage	Damage/ Change Description
------------------------	----------------	----------------	--------------	----------------------	-----------------------------	-----------------------	-----------------------------------

NONE

1 (c) (ii). **Encapsulation**

It is recommended that the asbestos containing materials in the following areas with the school districts buildings be encapsulated by a State of Ohio licensed Contractor. This recommendation is made after evaluating the information contained in the building inspection survey for ACM, and is based upon the assessments made by the accredited building inspector. Final clearance samples are required to be collected for each project work area by a State licensed Asbestos Hazard Evaluation Specialist, and analyzed by a NVLAP accredited laboratory using either the AHERA protocol for TEM samples or the NIOSH 7400 method for PCM samples.

SCHOOL NAME: FIRELANDS LOCAL SCHOOL DISTRICT

Functional Area	Rm. No.	Fl. No.	SF LF	Material Type	Material Description	Percent Damage	Damage/ Change Description
------------------------	----------------	----------------	--------------	----------------------	-----------------------------	-----------------------	-----------------------------------

NONE

1 (c) (iii). **Enclosure**

It is recommended that the asbestos containing materials in the following areas within the school districts buildings be enclosed in an airtight enclosure by a State of Ohio licensed Contractor. This recommendation is made after evaluating the information contained in the building inspection survey for ACM, and is based upon the assessments made by the accredited building inspector. Final clearance samples are required to be collected for each project work area by a State licensed Asbestos Hazard Evaluation Specialist, and analyzed by a NVLAP accredited laboratory using either the AHERA protocol for TEM samples or the NIOSH 7400 method for PCM samples.

SCHOOL NAME: FIRELANDS LOCAL SCHOOL DISTRICT

Functional Area	Rm. No.	Fl. No.	SF LF	Material Type	Material Description	Percent Damage	Damage/ Change Description
-----------------	---------	---------	-------	---------------	----------------------	----------------	----------------------------

NONE

1 (c) (iv). **Repair**

It is recommended that the asbestos containing materials in the following areas with the school districts buildings be repaired by a State of Ohio licensed Contractor, or properly trained school district employees who have completed the 16-hour training as required in the AHERA regulations. After the material has been repaired, it will be included in the school districts Operations and Maintenance Program (O&M). This recommendation is made after evaluating the information contained in the building inspection survey for ACM, and is based upon the assessments made by the accredited building inspector.

SCHOOL NAME: FIRELANDS LOCAL SCHOOL DISTRICT

Functional Area	Rm. No.	Fl. No.	SF LF	Material Type	Material Description	Percent Damage	Damage/ Change Description
-----------------	---------	---------	-------	---------------	----------------------	----------------	----------------------------

NONE

1 (c) (v). Operations and Maintenance

It is recommended that the asbestos containing materials in the following areas within the school districts buildings be included in the school districts Operations and Maintenance Program (O&M). This inventory also includes the materials listed in the previous sections that are recommended to be removed, encapsulated, enclosed or repaired to a non-friable condition. This recommendation is made after evaluating the information contained in the building inspection survey for ACBM, and is based upon the assessments made by the accredited building inspector.

SCHOOL NAME: FIRELANDS ELEMENTARY

Functional Area	Rm. No.	Fl. No.	SF LF	Material Type	Material Description	Percent Damage	Damage Description
BOILER ROOM	1ST.FL.		1 OTHER	ASBESTOS INSULATED FIRE DOOR		0%	NONE
EAST CORRIDOR	1ST.FL.		540 SQ.	ASBESTOS WALL PANELS		0%	NONE
EAST CORRIDOR	1ST.FL.		1200 SQ.	VAT GREY FLOOR TILE & MASTIC		0%	NONE
GYMNASIUM	1ST.FL.		1800 SQ.	VAT GREY FLOOR TILE & MASTIC		0%	NONE
BOYS LOCKER ROOM	1ST.FL.		30 TSI	CEMENTITIOUS PIPE ELBOWS & JOINTS		0%	NONE
GIRLS LOCKER ROOM	1ST.FL.		8 TSI	CEMENTITIOUS PIPE ELBOWS & JOINTS		0%	NONE
GIRLS LOCKER STOR.	1ST.FL.		6 TSI	CEMENTITIOUS PIPE ELBOWS & JOINTS		0%	NONE
KITCHEN	1ST.FL.		10 TSI	CEMENTITIOUS PIPE ELBOWS & JOINTS		0%	NONE
STAGE	1ST.FL.		1200 SQ.	VAT GREY FLOOR TILE & MASTIC		0%	NONE
TUTOR ROOM	1ST.FL.		100 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
BACK GYM CORRIDOR	1ST.FL.		500 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.20		800 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	28/29		1000 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
PRACTICE ROOM	RM.1		80 SQ.	ASBESTOS BOARD PANEL		0%	NONE
PRACTICE ROOM	RM.1		50 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
PRACTICE ROOM	RM.2		80 SQ.	ASBESTOS BOARD PANEL		0%	NONE
PRACTICE ROOM	RM.2		50 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
MUSIC OFFICE	1ST.FL.		100 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
INSTRUMENT STORAGE	1ST.FL.		120 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.21		800 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.27		800 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.23		800 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.26		800 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.25		800 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.24		800 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
NORTH CORRIDOR	1ST.FL.		200 SQ.	ASBESTOS BOARD PANEL		0%	NONE
NORTH CORRIDOR	1ST.FL.		1200 SQ.	VAT GREY FLOOR TILE & MASTIC		0%	NONE
JANITORS CLOSET	1ST.FL.		10 TSI	CEMENTITIOUS PIPE ELBOWS & JOINTS		0%	NONE
PIPE CHASE	1ST.FL.		30 TSI	CEMENTITIOUS PIPE ELBOWS & JOINTS		5%	SMALL HOLES
OFFICE CORRIDOR	1ST.FL.		300 SQQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
CENTRAL OFFICE	1ST.FL.		250 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
COPY ROOM	1ST.FL.		100 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
GUIDANCE OFFICE	1ST.FL.		100 SQ.	VAT GREY FLOOR TILE & MASTIC		0%	NONE
BOOK STORAGE	1ST.FL.		100 SQ.	VAT GREY FLOOR TILE & MASTIC		0%	NONE
PIPE CHASE	1ST.FL.		10 TSI	CEMENTITIOUS PIPE ELBOWS & JOINTS		10%	DAMAGED MATERIAL
WEST CORRIDOR	1ST.FL.		1100 SQ.	ASBESTOS BOARD PANEL		0%	NONE
WEST CORRIDOR	1ST.FL.		2500 SQ.	VAT GREY FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.1		800 SQ.	VAT WHITE FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.2		800 SQ.	VAT WHITE FLOOR TILE & MASTIC		0%	NONE

1 (c) (v). Operations and Maintenance

It is recommended that the asbestos containing materials in the following areas within the school districts buildings be included in the school districts Operations and Maintenance Program (O&M). This inventory also includes the materials listed in the previous sections that are recommended to be removed, encapsulated, enclosed or repaired to a non-friable condition. This recommendation is made after evaluating the information contained in the building inspection survey for ACBM, and is based upon the assessments made by the accredited building inspector.

SCHOOL NAME: FIRELANDS ELEMENTARY

Functional Area	Rm. No.	Fl. No.	SF LF	Material Type	Material Description	Percent Damage	Damage Description
CLASSROOM	RM.3		800 SQ.	VAT WHITE FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.12		800 SQ.	VAT GREY FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.4		800 SQ.	VAT WHITE FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.11		800 SQ.	VAT GREY FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.5		800 SQ.	VAT BEIGE FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.10		800 SQ.	VAT RED FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.6		800 SQ.	VT BEIGE FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.9		800 SQ.	VAT RED FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.8		800 SQ.	VAT RED FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.7		800 SQ.	VT BEIGE FLOOR TILE & MASTIC		0%	NONE
JANITORS CLOSET	1ST.FL.		20 TSI	CEMENTITIOUS PIPE ELBOWS & JOINTS		0%	NONE
PIPE CHASE	1ST.FL.		10 TSI	CEMENTITIOUS PIPE ELBOWS & JOINTS		0%	NONE
TANK ROOM			125 TSI	ASBESTOS TANK INSULATION		0%	NONE
TANK ROOM			1 TSI	CEMENTITIOUS PIPE ELBOWS & JOINTS		0%	NONE

1 (c) (v). Operations and Maintenance

It is recommended that the asbestos containing materials in the following areas within the school districts buildings be included in the school districts Operations and Maintenance Program (O&M). This inventory also includes the materials listed in the previous sections that are recommended to be removed, encapsulated, enclosed or repaired to a non-friable condition. This recommendation is made after evaluating the information contained in the building inspection survey for ACBM, and is based upon the assessments made by the accredited building inspector.

SCHOOL NAME: SOUTH AMHERST MIDDLE SCHOOL

Functional Area	Rm. No.	Fl. No.	SF LF	Material Type	Material Description	Percent Damage	Damage Description
BOILER ROOM				1	ASBESTOS INSULATED FIRE DOOR	0%	NONE
CORRIDOR	BASEMENT		45 FT.		BLOCK PIPE INSULATION	0%	NONE
ART ROOM	RM. 090		15 FT		BLOCK PIPE INSULATION	0%	NONE
ART ROOM	RM.090		800 SQ.		VAT BROWN/BEIGE FLOOR TILE & MASTIC	0%	NONE/UNDER NEW TILE
BOYS RESTROOM	BASEMENT		40 FT.		BLOCK PIPE INSULATION	0%	NONE
STORAGE ROOM	RM.91		55 FT.		BLOCK PIPE INSULATION	0%	NONE
STORAGE ROOM	BASEMENT			10	CEMENTITIOUS PIPE ELBOWS & JOINTS	0%	NONE
STORAGE ROOM	BASEMENT		100 SQ.FT		TANK INSULATION	0%	NONE
GIRLS RESTROOM	BASEMENT		50 FT.		BLOCK PIPE INSULATION	0%	NONE
ART ROOM	BASEMENT		60 FT.		BLOCK PIPE INSULATION	0%	NONE
MAIN CORRIDOR	1ST.FL.		50 FT.		BLOCK PIPE INSULATION	0%	NONE
CLASSROOM	RM.101		10 FT.		PAPER PIPE INSULATION	0%	NONE
STAGE CORRIDOR	1ST.FL.			4	CEMENTITIOUS PIPE ELBOWS & JOINTS	0%	NONE
OFFICE CORRIDOR	1ST.FL.		900 sq.		ASBESTOS BOARD PANEL	0%	NONE
CAFETERIA	1ST.FL.		1200 SQ.		VAT BROWN FLOOR TILE & MASTIC	0%	NONE
KITCHEN	1ST.FL.		250 SQ.		VT WHITE FLOOR & MASTIC	0%	NONE
CAFETERIA RESTROOM	1ST.FL.		30 SQ.		VT WHITE FLOOR & MASTIC	0%	NONE
JANITORS CLOSET	1ST.FL.		35 FT.		PAPER PIPE INSULATION	0%	NONE
OFFICE STORAGE	1ST.FL.		100 SQ.		VAT GREY FLOOR TILE & MASTIC	0%	NONE
OFFICE STORAGE	1ST.FL.		12 FT.		PAPER PIPE INSULATION	0%	NONE
PRINCIPAL STORAGE	1ST.FL.		50 SQ.		VAT GREY FLOOR TILE & MASTIC	0%	NONE
LIBRARY OFFICE	RM.129		35 FT.		PAPER PIPE INSULATION	0%	NONE
CLASSROOM	RM. 130		800 SQ.		VT WHITE FLOOR & MASTIC	0%	NONE
LIBRARY	1ST.FL.		35 FT.		PAPER PIPE INSULATION	0%	NONE/ABOVE CEILING
CORRIDOR	1ST.FL.		60 FT.		PAPER PIPE INSULATION	5%	EXPOSED ENDS
CORRIDOR	2ND. FL.		600 SQ.		ASBESTOS BOARD PANEL	0%	NONE
CLASSROOM	RM. 221		800 SQ.		VAT BROWN FLOOR TILE & MASTIC	0%	NONE
CLASSROOM	RM.222		800 SQ.		VAT GREEN/GREY FLOOR TILE & MASTIC	0%	NONE
CLASSROOM	RM.217		800 SQ.		VAT BROWN FLOOR TILE & MASTIC	0%	NONE
OFFICE	RM.219		100 SQ.		VAT BROWN FLOOR TILE & MASTIC	0%	NONE
FACULTY LOUNGE	2ND.FL.		150 SQ.		VAT BROWN FLOOR TILE & MASTIC	0%	NONE
CLASSROOM	RM.209		800 SQ.		VT GREEN FLOOR TILE & MASTIC	0%	NONE
CLASSROOM	RM.214			1	TRANSITE SINK	0%	NONE
CLASSROOM	RM.214		800 SQ.		VAT GREY FLOOR TILE & MASTIC	0%	NONE
CHEMISTRY LAB	RM.220		150 SQ.		TRANSITE COUNTERTOP & HOOD	0%	NONE
CHEMISTRY LAB	RM.220		800 SQ.		VAT WHITE FLOOR TILE & MASTIC	0%	NONE
CLASSROOM	RM.202		800 SQ.		VAT WHITE FLOOR TILE & MASTIC	0%	NONE
OFFICE WORKROOM	2ND.FL.		120 SQ		VAT WHITE FLOOR TILE & MASTIC	0%	NONE
CEILING PLENUM	2ND.FL.		850 SQ.		CEILING PLASTER	5%	DAMAGED MATERIAL

1 (c) (v). Operations and Maintenance

It is recommended that the asbestos containing materials in the following areas within the school districts buildings be included in the school districts Operations and Maintenance Program (O&M). This inventory also includes the materials listed in the previous sections that are recommended to be removed, encapsulated, enclosed or repaired to a non-friable condition. This recommendation is made after evaluating the information contained in the building inspection survey for ACBM, and is based upon the assessments made by the accredited building inspector.

SCHOOL NAME: BOARD OFFICE

Functional Area	Rm. No.	Fl. No.	SF LF	Material Type	Material Description	Percent Damage	Damage Description
FACULTY ROOM	1ST.FL.		10 TSI	CEMENTITIOUS PIPE ELBOWS & JOINTS		0%	NONE
LIBRARY AREA	1ST.FL.		1200 SQ.	VAT WHITE FLOOR TILE & MASTIC		0%	NONE
FACULTY RESTROOM	1ST.FL.		30 SQ.	VAT WHITE FLOOR TILE & MASTIC		0%	NONE
PRINCIPAL OFFICE	1ST.FL.		120 SQ.	VAT WHITE FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.100		800 SQ.	VAT WHITE/BLUE FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.101		800 SQ.	VAT WHITE/BLUE FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.102		800 SQ.	VAT WHITE/BLUE FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM. 103		800 SQ.	VAT WHITE/BLUE FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.104		800 SQ.	VAT WHITE/BLUE FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.105		800 SQ.	VAT WHITE/BLUE FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.130		800 SQ.	VAT WHITE/BLUE FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.132		800 SQ.	VAT WHITE/BLUE FLOOR TILE & MASTIC		0%	NONE
STORAGE CLOSET			100 SQ.	VAT WHITE FLOOR TILE & MASTIC		0%	NONE
STORAGE CLOSET			2 TSI	CEMENTITIOUS PIPE ELBOWS & JOINTS		0%	NONE
CLASSROOM	RM.108		800 SQ.	VAT WHITE/BLUE FLOOR TILE & MASTIC		0%	NONE
STORAGE CLOSET	RM.108		100 SQ.	VAT WHITE FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.106		800 SQ.	VAT WHITE/BLUE FLOOR TILE & MASTIC		0%	NONE
CEILING PLENUM	1ST.FL.		100 TSI	CEMENTITIOUS PIPE ELBOWS & JOINTS		0%	NONE

1 (c) (v). Operations and Maintenance

It is recommended that the asbestos containing materials in the following areas within the school districts buildings be included in the school districts Operations and Maintenance Program (O&M). This inventory also includes the materials listed in the previous sections that are recommended to be removed, encapsulated, enclosed or repaired to a non-friable condition. This recommendation is made after evaluating the information contained in the building inspection survey for ACBM, and is based upon the assessments made by the accredited building inspector.

SCHOOL NAME: FIRELANDS HIGH SCHOOL

Functional Area	Rm. No.	Fl. SF No. LF	Material Type	Material Description	Percent Damage	Damage Description
BOILER ROOM	1ST.FL.	1 TSI	ASBESTOS INSULATED FIRE DOOR		0%	NONE
WEIGHT ROOM	RM. 200	650 SQ.	VAT RED FLOOR TILE & MASTIC		0%	NONE
WEIGHT ROOM	RM. 200	4 TSI	CEMENTITIOUS PIPE ELBOWS & JOINTS		0%	NONE
OFFICE	RM. 200	100 SQ.	VAT RED FLOOR TILE & MASTIC		0%	NONE
SHOP TOOL RM.	1ST.FL.	100 SQ.	VAT RED FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.156	10 TSI	CEMENTITIOUS PIPE ELBOWS & JOINTS		0%	NONE
VO/AG SHOP	RM.122	7 TSI	CEMENTITIOUS ELBOWS ON ROOF DRAINS		0%	NONE
CLASSROOM	RM.120	650 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
OFFICE	RM.122	100 SQ.	VAT WHITE FLOOR TILE & MASTIC		0%	NONE/ UNDER CARPET
FACULTY WORKROOM	1ST.FL.	150 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
CONFERENCE ROOM	1ST.FL.	100 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
AV WORKROOM	1ST.FL.	120 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.124	650 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
MACHINE BAY	RM.129	150 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
MACHINE BAY	RM.129	500 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.126	650 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
MUSIC ROOM	1ST.FL.	1000SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
PRACTICE ROOM	1ST.FL.	50 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
PRACTICE ROOM	1ST.FL.	50 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
MUSIC OFFICE	1ST.FL.	100 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
INSTRUMENT STORAGE	1ST.FL.	150 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.121	650 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.123	650 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
STORAGE ROOM	1ST.FL.	100 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
NORTH CORRIDOR	1ST.FL.	1200 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.108	650 SQ.	VT RED FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.109	650 SQ.	VT GREEN FLOOR TILE & MASTIC		0%	NONE
NW CORRIDOR	1ST.FL.	180 SQ.	CEMENT ASBESTOS WALL BOARD		0%	NONE
NW CORRIDOR	1ST.FL.	1000 SQ.	VAT GREEN FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.111	650 SQ.	VAT BROWN/BEIGE FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.110	650 SQ.	VAT BROWN/BEIGE FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.113	650 SQ.	VAT BROWN/BEIGE FLOOR TILE & MASTIC		0%	NONE
CONFERENCE ROOM	1ST.FL.	200 SQ.	VAT RED FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	139/141	650 SQ.	VAT BROWN/BEIGE FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.107	650 SQ.	VT GREEN FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.105	160 SQ.	TRANSITE COUNTERTOP		0%	NONE
CLASSROOM	RM.104	650 SQ.	VT RED FLOOR & MASTIC		0%	NONE
CLASSROOM	RM. 113	650 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
PREP ROOM	RM.103	120 SQ.	VT GREEN FLOOR & MASTIC		0%	NONE
CLASSROOM	RM.103	40 SQ.	TRANSITE COUNTERTOPS		0%	NONE

1 (c) (v). Operations and Maintenance

It is recommended that the asbestos containing materials in the following areas within the school districts buildings be included in the school districts Operations and Maintenance Program (O&M). This inventory also includes the materials listed in the previous sections that are recommended to be removed, encapsulated, enclosed or repaired to a non-friable condition. This recommendation is made after evaluating the information contained in the building inspection survey for ACBM, and is based upon the assessments made by the accredited building inspector.

SCHOOL NAME: FIRELANDS HIGH SCHOOL

Functional Area	Rm. No.	Fl. SF No. LF	Material Type	Material Description	Percent Damage	Damage Description
CLASSROOM	RM.103	650 SQ.	VT GREEN FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.102	650 SQ.	VAT RED FLOOR TILE & MASTIC		0%	NONE
CLASSROOM	RM.101	650 SQ.	VT GREEN FLOOR TILE & MASTIC		0%	NONE
PREP ROOM	RM.101	2 tsi	CEMENTITIOUS PIPE ELBOWS & JOINTS		0%	NONE
JANITOR STORAGE	1ST.FL.	10 FT.	PAPER PIPE INSULATION		0%	NONE
CLASSROOM	RM.115	650 SQ.	VAT RED FLOOR TILE & MASTIC		0%	NONE
STAGE	1ST.FL.	100 FT.	BLOCK PIPE INSULATION		0%	NONE
STAGE	1ST.FL.	80 FT.	BLOCK PIPE INSULATION		0%	NONE
KITCHEN CORRIDOR	1ST.FL.	20 FT.	PAPER PIPE INSULATION		2%	EXPOSED END
KITCHEN	1ST.FL.	250 SQ.	VT WHITE FLOOR & MASTIC		0%	NONE
CAFETERIA	1ST.FL.	1500 SQ.	VT WHITE FLOOR & MASTIC		0%	NONE
KITCHEN RESTROOM	1ST.FL.	15 FT.	BLOCK PIPE INSULATION		0%	NONE
RESTROOM	1ST.FL.	150 SQ.	VAT BROWN FLOOR TILE & MASTIC		0%	NONE
CENTRAL OFFICE	1ST.FL.	250 SQ.	VT GREEN FLOOR TILE & MASTIC		0%	NONE
CENTRAL OFFICE	1ST.FL.	12 FT.	BLOCK PIPE INSULATION		0%	NONE
ASST PRINCIPAL OFFICE	1ST.FL.	20 SQ.	VT BLACK FLOOR & MASTIC		0%	NONE
ASST PRINCIPAL OFFICE	1ST.FL.	15 FT.	BLOCK PIPE INSULATION		0%	NONE
ASST PRINCIPAL OFFICE	1ST.FL.	120 SQ.	VT GREY FLOOR & MASTIC		0%	NONE
ASST PRINCIPAL OFFICE	1ST.FL.	10 FT.	BLOCK PIPE INSULATION		0%	NONE
CONFERENCE ROOM	1ST.FL.	150 SQ.	VT GREEN FLOOR TILE & MASTIC		0%	NONE
CONFERENCE ROOM	1ST.FL.	12 FT.	BLOCK PIPE INSULATION		5%	SMALL TEAR
OFFICE RESTROOM	1ST.FL.	30 SQ.	VT GREEN FLOOR TILE & MASTIC		0%	NONE
OFFICE STORAGE	1ST.FL.	6 FT.	BLOCK PIPE INSULATION		0%	NONE
CLINIC	1ST.FL.	200 SQ.	VT GREEN FLOOR TILE & MASTIC		0%	NONE
PRINCIPAL OFFICE	1ST.FL.	240 SQ.	VT GREY FLOOR & MASTIC		0%	NONE
PRINCIPAL OFFICE	1ST.FL.	15 FT.	BLOCK PIPE INSULATION		0%	NONE
PA ROOM	1ST.FL.	50 SQ.	VT GREEN FLOOR TILE & MASTIC		0%	NONE
CLASSROOM/ A.D.	RM.100	650 SQ.	VT GREEN FLOOR TILE & MASTIC		0%	NONE
STORAGE ROOM	RM.100	100 SQ.	VT GREEN FLOOR TILE & MASTIC		0%	NONE
STORAGE ROOM	RM.100	10 FT.	BLOCK PIPE INSULATION		0%	NONE
CLASSROOM	RM.203	650 SQ.	VAT RED FLOOR TILE & MASTIC		0%	NONE
FACULTY MEN'S R.R.	2ND.FL.	30 SQ.	VT GREY FLOOR TILE & MASTIC		0%	NONE
FACULTY WOMEN'S R.R.	2ND.FL.	30 SQ.	VT GREEN FLOOR TILE & MASTIC		0%	NONE
CEILING PLENUM	1ST.FL.		BLOCK PIPE INSULATION ABOVE CEILING		5%	WATER DAMAGE
CLASSROOM	RM. 302	650 VAT	VAT RED FLOOR TILE & MASTIC		0%	NONE
CORRIDORS		2500 SQ.	TRANSITE WALL PANELS		0%	NONE

1 (d). **RECOMMENDATIONS**

The above recommendations were prepared by Darrin Demshar of Monit-Air Group Inc, Ohio Hazard Evaluation Specialist No.34336.

A handwritten signature in black ink, appearing to be 'D. Demshar', written in a cursive style.

Darrin Demshar
President